


Eco Rewards Extension to Wildridings Primary

28/08/26 v1.1

Wildriding - Location



- New locations proposed and installed



See <https://www.ecorewards.co.uk/bracknell/eco-rewards-locations>

Wildriding - new signs



→ School entrances

1





See <https://www.ecorewards.co.uk/bracknell/eco-rewards-locations>


West of School



Behind School



Rec Ground – not yet installed



General Risk Assessment – QR code

What is the hazard	Level of Risk	Mitigation	Further Action Required
Electric shock from contact due to fault in lamp column/cabinet	Very Low	Inspect column	Remove sign if column damaged
Cut from sharp edges	Low	Corners rounded and installed at height	Replace damaged signs
Sign falls & injures pedestrian	Low	Secure fixing, 2 straps	Check secure regularly
Pedestrian collides with sign	Low	Ensure not protruding into path way and at suitable height	
Pedestrians collide while reading sign	Low	Ensure space to pass	
COVID 19 – risk of virus transmission	Low	Users should have limited contact	Advise not to touch and wash hands/sanitise
Group of ER users block pavement or X-ing leading to people in road	Medium	Position of sign away from kerb	Check each location and monitor peak usage

The only significant health and safety risk identified is the last one, which needs to be considered at each location and monitored as queue of ER scheme users could build up and lead to pedestrians standing in road way